CARLY DIAGNOSTICS REPORT

BMW 7 series (2009)

ОКТ. 28 2020

STATUS	TOTAL ISSUES	HEALTHY SYSTEMS
Very Bad	**27**	**31**

Issues (9)

Engine

Fault code: 243000	Glow plug cylinder 5 control: interruption
Fault code: INFO 27AB00	DDE control unit internal (cyclic authentication): record check is not okay

Seat Belt Tensioner Right

Fault code: INFO 4E0008	VSM event vehiclestate
Fault code: INFO 4E005A	ALG speed input error
Fault code: INFO 4E005B	ALG acc lat input error
Fault code: INFO 4E005C	ALG acc long input error
Fault code: INFO 4E005D	ALG yaw rate input error
Fault code: INFO 4E005E	ALG steering angle input error
Fault code: INFO 4E005F	ALG brake input error
Fault code: INFO 4E0061	ALG emergency braking error
Fault code: INFO 4E0062	ALG evasive manoeuvre error

Fault code: INFO 4E0063	ALG body slip error
Fault code: INFO 4E0064	ALG over under steering error
Fault code: INFO 4E0065	ALG under steering drift error
Fault code: INFO 4E0066	ALG trbs error

Active Steering

Fault code: INFO 16004C	SECU - DEM event KFC KL30 undervoltage (secu)
Fault code: INFO 16004E	SECU - DEM event KFC KL15 undervoltage (secu)

Foot Well Module

Fault code: 800FB5	Exterior mirrors poti defective right
Fault code: 800FB6	Defective exterior mirror heating or elektro.-crome left
Fault code: 030015	Window driver-side: invalid characteristic, no standardization exists

Car Access System

Fault code: 9307A8	DAYS passenger door / page (BFT): invalid current value to unlocking line
Fault code: 9307B6	DAYS passenger door / side rear (BFTH): invalid current value to unlocking line

Rear Seat (driver side)

Fault code: 802A08	PIA: porting limited due to lack of calibration

Integr. Chassis Module

Fault code: D0195B	Message error (warning lane change, ID: waRN inch) channel: HC2 - timeout / Message error (warning lane change, ID: waRN inch) - timeout

Air Conditioning

Fault code: 8011D7	Parking heater, water pump short circuit to positive or open circuit / EKMV: OBD current sensor phase 2 short circuit to positive
Fault code: 8011E4	Parking heater: EOL checksum error / EKMV: OBD memory error EEPROM

Night Vision

Fault code: 800494	Nivi camera: internal software error / Nivi camera: no communication to the control unit

Healthy Systems (31)

- Infotainment
- Electr. Ride Height Control
- Passenger Seat
- TV Tuner
- Damper Rear Right
- Damper Front Left
- Air Conditioning
- Park Distance Control (PDC)
- Vertical Dynamic Management
- Head-Up Display
- Electronic Parking Brake
- Rear Seat (passenger side)
- Tailgate
- Central Control Unit

- Roof Control Panel
- Steering Column Switch Cluster
- Transmission
- Video Switch
- Gear Lever
- Driver Assistant
- Damper Front Right
- Instrument Cluster
- Fuel Pump
- Junction Box Module
- Telephone
- Airbag
- Rear Axle
- Damper Rear Left
- Central Info Display